


The MACHINE marking system...



SAFETY PICTOGRAMS

Read operator's instructions	Ear protection must be worn	Hand protection must be worn	Eye protection must be worn
Danger : risk of cut	Danger : risk of cut	Never move the machine with the blade running idle	Emergency stop switch

INFORMATION PICTOGRAMS

Blade direction of rotation	
Do not lift the machine from here	Lift from here